

LDWASF
4.4.1
2/4/10



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

February 4, 2010

Mr. Michael Sibley
U.S. Environmental Protection Agency
US EPA Region 10
ECL-116
1200 6th Avenue, Suite 900
Seattle, WA 98101

Re: Request for EPA to mitigate PCB contamination in the 24 inch Stormwater Line at Jorgensen Forge located at 8531 East Marginal Way South, Seattle, Washington.

Dear Mr. Sibley,

The Washington State Department of Ecology (Ecology) requests that you mitigate the PCB contamination in the 24 inch stormwater line located at the Jorgensen Forge Corporation site.

The 24 inch stormwater line is contaminated with PCBs and other contaminants which pose a threat to the Lower Duwamish Waterway by causing environmental damage and posing a risk to human health.

Ecology is unable to accomplish the mitigation task primarily because:

- Current severe budget constraints
- The mitigation requires immediate action without being ensnarled in a legal battle

While Ecology has clear legal authority to compel Jorgensen Forge to clean up the 24 inch stormwater line it is likely that the process could take a long time. Ecology feels that Jorgensen Forge would tie this project up in legal arguments before they cooperated in a cleanup of the 24 inch line. They believe that the pollution in the 24 inch line came from the adjacent Boeing facility, and that are being unfairly asked to shoulder the burden of the cleanup. They could appeal as innocent purchasers or as the victims of third party actions as provided for under Chapter 70.105D RCW. Currently Ecology doesn't have the "credible evidence" required by Chapter 173-340 WAC to name Boeing as a PLP (same as PRP).

Ecology authority under water quality law is similarly limited because ownership of the stormwater line is unclear as is the list of its operators.



USEPA SF



1367598




February 4, 2010

Page 2

Ecology Spills Program may have authority, but they currently do not have funds to take on a project as large as the 24 inch stormwater line. Thank you for your interest in assisting with the mitigation of this stormwater line. Please call me at (425) 649-7052 if you have any further questions.

Sincerely,

A handwritten signature in cursive script, appearing to read "John Keeling".

John Keeling
Toxic Cleanup Program

cc: Louise Bardy, Ecology
Ching-Pi Wang, Ecology
Rick Thomas, Ecology
Nels Johnson, AG

Enclosure (1)

List of Contacts:

Jorgensen Forge

Mr. Ron Altier
Vice President
Jorgensen Forge Corporation
8531 East Marginal Way
Seattle, WA 98108-4018
(206) 676-9249
raltier@jorgensenforge.com

Ryan Barth
Anchor QEA, LLC
1423 3rd Avenue, Suite 300
Seattle, Washington 98101
(206) 903-3334
rbarth@anchorqea.com

Boeing

William D Ernst
The Boeing Company
P. O. Box 3707-MC1W-12Seattle, WA 98124
(425) 891-7724
william.d.ernst@boeing.com

King County Boeing Field

Peter Dumaliang, Environmental Scientist III
Airport Engineering
King County International Airport/Boeing Field
7277 Perimeter Rd. S., Seattle WA 98108
Peter.Dumaliang@kingcounty.gov
Direct: (206) 296-7597
Fax: (206) 296-0190
Cell: (206) 391-7577

City of Tukwila

Ryan Larson
City of Tukwila
Public Works Department
6300 Southcenter Boulevard
Tukwila, WA 98188-2544
rlarson@ci.tukwila.wa.us
(206) -431-2456